

Pool no:

## **NSW SWIMMING POOL REGISTER**

## **Certificate of Non-compliance**

Clause 21 - Swimming Pools Regulation 2018

406acab0

| Property address:   |   | 61 TRENTBRIDGE ROAD BELROSE                           |   |
|---|---|---|---|
| Date of inspection:   |   | 04 February 2025                                      |   |
| Expiry date:  |   | 04 February 2026                                      |   |
| Issuing authority:  |   | Jennifer Elaine Rose - Registered Certifier - bdc2862 |   |
| Did not comply with AS1926.1 (2012).  |   |   |   |
| The swimming pool at the above property DOES NOT COMPLY with Part 2 of the Swimming Pools Act 1992. Please refer to the registered certifier's notice, issued under section 22E of the Swimming Pools Act 1992, for detailed reasons of non-compliance and rectification works required to render the swimming pool compliant with the applicable standard. |   |   |   |
| The swimming pool poses a significant risk to public safety□  |   |   |   |
| The swimming pool does not pose a significant risk to public safety 🗵   |   |   |   |
| Non-compliance area/s:  |   |   |   |
| Boundary fence  | X | Doors   |   |
| Fence height  | X | Fence panels/gaps                                     | X |
| Gate closure  |   | Gate latch  |   |
| Non-ancillary structure   |   | Non-climbable zones                                   | X |
| Signage   | X | Window  |   |
| Other (see text box below)  | X |   |   |
| walk around from retaining wall   |   |   |   |
|   |   |   |   |

This certificate expires on issuing of a certificate of compliance or 12 months after the date of issue, whichever occurs first.

Purchasers of a property with a non-compliant swimming pool barrier have 90 days from the date of settlement to fix any areas of non-compliance.